



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

December 8, 2006

Jared Anderson
Anderson Supply Co.
2116 South 750 West
Woods Cross, UT 84087

Subject: Notice of File Closure, Anderson Supply Mine, S/049/018, Task ID# 1398,
Utah County, Utah

Dear Mr. Kelley:

The Anderson Supply Mine permit, file number S/049/018, located in Utah County, Utah, will now be closed and the file retired.

On May 11, 2006 a site inspection was performed and it was determined that this project was never initiated. It was determined that the disturbances at the site were not caused by you, or under your authority. It was also determined that much of your permitted area is now part of the Eagle Mountain Subdivision. (housing project). It is also the Division's understanding that the leases you had for this site have expired.

The Division hereby releases you from further reclamation responsibility at this site. If you wish to conduct any future mining related activity in this area, you will need to submit a new notice and surety for approval prior to creating any disturbance.

If you have any questions or concerns regarding this action, please contact me at (801) 538-5258 or Lynn Kunzler at (801) 538-5310. Thank you for your time and consideration in completing the required reclamation on this project.

Sincerely,

for Susan M. White
Susan M. White
Mine Program Coordinator
Minerals Regulatory Program

SMW:lk:pb
P:\GROUPS\MINERALS\WP\M049-Utah\S0490018-AndersonSupply\final\Ret-06012006.doc



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
June 1, 2006

Supervisor QAZ

Mine Name: Anderson Supply Mine
Operator Name: Anderson Supply

Permit number: M0490018
Inspection Date: May 11, 2006
Time: 10:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Jared Anderson
Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Operator requested inspection to close file.

Inspection Summary:
1. This site has not been active since the operator permitted an old historic clay pit. The operator has lost his lease for the mineral with SITLA and the private surface. Much of the mine site is now part of the Eagle Mountain Subdivision (housing).

Photos were taken of site conditions

Conclusions and Recommendations:
1. Since the permittee has not created any of the disturbance and no longer has control of the mineral/surface estates, it is recommended that this file be close.

Inspector's Signature LK
LK:pb
File Name and Path

Date: June 1, 2006